

PNEUMATIC CALIBRATION HAND PUMP

Generates up to 600 psi (40 bar), Comfort Grip Handles



1/8 BSP WITH
1/8 NPT ADAPTER

1/8 NPT
PLUG
SLIDE
BUTTON

7-3/32
[180.1]

8-41/64
[219.48]

1/4 BSP WITH 1/4 NPT ADAPTER

The **SERIES PCHP** Pneumatic Calibration Hand Pump sources pressure and vacuum to check calibration of gages, switches, transmitters, and recorders. The contoured cushion handles provide extra comfort while preventing the pump from sliding.

FEATURES/BENEFITS

- · Oversized check valve maintain smooth operation
- · Dual O-rings on pistons ensure no leaks

APPLICATIONS

- · Instrument calibration
- Laboratories
- Production areas

MODEL CHART		
Model	Description	
PCHP-1	Pneumatic calibration hand pump	
PCHP-1K	Pneumatic calibration hand pump with hose kit	

SPECIFICATIONS

Output Ranges: -28 in Hg to 600 psi (-0.945 to 40 bar).

Process Connection: 1/4" NPT/BSP. Gage Connection: 1/8" NPT/BSP.

Materials: SS fittings, anodized aluminum housing, plastic/rubber handles, and

nitrile O-rings.

Weight: 2 lb (0.91 kg).

ACCESSORIES			
Model	Description		
PCHP-HK	High pressure hose		